# X2150 Connections

Ports

There are seven serial port outputs on the X2150, six RS485 and one RS232. All six RS485 ports are available from two, 8-way RJ45 connectors and a standard D9 male connector is provided for the RS232 interface.

CN1: RS232 Port 7	CN2: RS485 Ports 1 - 3	CN3: RS485 Ports 4 - 6	CN4: Power 9 - 12v dc

RS232

2	TXD
3	RXD
4	DSR
5	GND
6	DTR
7	CTS
8	RTS

Power input
9v – 12v DC 500mA
Centre pin=+ve

CAT 5 Lead

CAT 5 Lead

1 B (-)   3 B (+)   4 B (-)   6 B (+)

1 A (+)   3 A (-)   4 A (+)   6 A (-)

2 B (-)   2 A (+)   5 B (-)   5 A (+)

GND

GND